

NEWS

October 30 , 2009

13-5, Kudankita 1-chome, Chiyoda-Tokyo 102-8202, Japan.

Telephone: (03) 3230-3923

Fax: (03) 3230-3431

URL: <http://www.riken.co.jp>

TO:RIK PISTON RING SET CUSTOMER :

RIKEN
RIKEN CORPORATION

Engine Type	Piston Ring			Surface Treatment	Set Type	RIK Set No.	Remarks
	Size	d1×h1×a1 (mm)					
Hyundai Santro HY01	67 x 1.2 x 2.3			GN	SV	40910	23040-02820
	67 x 1.2 x 2.8						
	67 x 2.5 x 2.5			GN			
Hyundai Santro (1.1L)	67 x 1.2 x 2.3			Cr1	SV	40990	23040-02950
	67 x 1.2 x 2.9						
	67 x 2.0 x 2.8			GN			
Hyundai G4CP (2.0L)	85 x 1.2 x 3.1			GN	SV	40325	23040-33110 23040-33140
	85 x 1.5 x 3.8			Cr1			
	85 x 3.0 x 2.8			GN			
Hyundai Y2 (2.4L)	86.5 x 1.5 x 3.5			Cr1	SV	40044	23040-32610
	86.5 x 1.5 x 3.8						
	86.5 x 4.0 x 3.4			Cr1			
Hyundai D6AB	130 x 3.297 x 5.4			Cr1	FM	40061	23040-83020 23040-83030
	130 x 3.0 x 5.3			Cr4			
	130 x 4.0 x 2.45						
Kia S2/XA	88.925 x 2.383 x 3.45			Cr1	FX	40043	K6Z0-11-SCO
	88.925 x 2.383 x 3.5						
	88.925 x 4.763 x 2.9						
Kia K4100	92.025 x 2.383 x 3.6			Cr1	FX	40047	K8Y1-11-SCO
	92.025 x 2.383 x 3.6			Cr1			
	92.025 x 4.763 x 2.9						

